
F I G. 1



F1G. 2




FIG. 3







FIG. 4A $\alpha > \beta$ Rattling tolerance


Eccentricity tolerance








F I G. 5





Pocket clearance β [mm]

Maximum displacement amount of cage in radial direction [mm]

FIG. 7

